

A117.1 2003 errata


1 March, 2007

- Page 41: In Section 504.8.1 change the section heading to “**Illumination level.**”
- Page 41: In Section 504.8.1 in the third line, change the word “luminance” to be “illuminance.” The sentence should read “.....10 foot-candles (108 lux) of illuminance measured at.....”
- Page 41: In Section 504.8.2 in the third line, change the word “luminance” to be “illuminance.” The sentence should read “.....stairway lighting so the illuminance level required by.....”
- Page 44: In Section 506 add a new section number and heading of “**Section 506.1 General**”. The section would then read:
- Section 506 Windows**
Section 506.1 General. Accessible windows shall have operable parts complying with Section 309.
- Page 51: In Figures 604.8.5 (a), 604.8.5 (b) and 604.8.5 (c) delete the word “min” from the 6 inch toe clearance dimension string.
- Page 79: In Table 802.10 revise the heading of the second column to be “Minimum required number of dispersed locations.”

A117.1 2003 errata

13 December, 2005

- Page VI: In the third line of the last paragraph, the reference should be to the “ICC A117.1-2003” instead of to the “ICC 300-2002.”
- Page IX: The number of professional members on the committee is 13 instead of 8. This also results in a total of 43 members instead of 38.
- Page 2: The figure should be labeled as “Fig. 104.3” instead of “Fig 104.2.”
- Page 7: Figure 302.2 should have the dimension string modified so that it only measures the height of the carpet pile and does not include the backing/pad. Figure should appear as shown below.



- Page 16: In Figure 403.5.1(a) the dimension string on the left side should read “48 Min” instead of “48 Max.”
- Page 54: In section 607.4 exception 2, the reference should be to section “1003.11.4” instead of “1003.11.9.”
- Page 57: In Figure 608.2.1, delete the word “min” from the dimension string at the top of the figure. The dimension string should read “36” instead of “36 min.”
- Page 57: In section 608.3 exception 2, the reference should be to section “1003.11.4” instead of “1003.11.9.”
- Page 59: In section 608.4 exception 2, the reference should be to section “1003.11.4” instead of “1003.11.9.”
- Page 90: In section 1003.3.2, the exception should reference “Sections 1003.11.5 through 1003.11.9” instead of “Section 1003.11.”

Page 91: In section 1003.11.1 the reference in the second line should be to section "1003.11.4" instead of to section "1003.11.9."

Page 95: In figure 1003.12.4, delete the dimension string which measures the bowl depth of the sink and the "6-1/2 max" dimension which is tied with it.