WOOD FRAME SOFT-STORY BUILDING RETROFIT PROGRAM

City of Los Angeles Department of Building and Safety



WOOD FRAME SOFT STORY BUILDINGS

- Wood frame buildings with the following criteria:
 - Built before 1980
 - Consists of 2 or more stories
 - Residential with 4 or more units and/or commercial



TUCK-UNDER PARKING






GARAGE DOORS/STEEL GATES CONSIDERED AS OPENINGS





COMMERCIAL STORE FRONT





WHY RETROFIT?

Without proper strengthening, the soft-story floor becomes weak and may suffer structural damage or complete failure during and/or after an earthquake.





SOLUTION! ELIMINATE SOFT, WEAK, OR OPEN WALL LINE

		5			


SHEAR WALLS

MOMENT FRAME

Concrete walls or masonry walls are prohibited.



STEP 1 COMPILE A LIST OF WOOD FRAME BUILDINGS BUILT BEFORE 1980



Obtain information from:

- Housing Department
- Tax Assessors
- Building Records

	_	_	_	1			_	_		cantiev	EST	ow		_
											LEVEL			Poss
		Comment								Building	CONC	Silea		
		Struct										r		ble
		ures of			-					more	RETE	Wall		Soft
		Interes	Story		First Floor Lateral					then 25	SLAB	<		Story
Address	Zip Code	t	Count	First Floor Use	System	Front	Back	Left	Right	ft.	1	4ft.	Comments/Description	(Y/N
2541 W CHANDLER BLVD	91607		2	Tuck Under Parking		0%	90%	10%	40%					Y
2535 W CHANDLER BLVD	91607		2	Tuck Under Parking		0%	90%	10%	40%					Y
2531 W CHANDLER BLVD	91607		2	Tuck Under Parking		0%	90%	10%	40%					Y
233 N WHITSETT AVE	91607			Tuck Under Parking	Wood Shear Wall	10%		90%		BALCONIE	S			Y
2159 W MAGNOLIA BLVD	91607		2	Tuck Under Parking	Wood Shear Wall	10%	80%	?	50%				CAN NOT SEE IN COURT	Y
216 N CORTEEN PL	91607			Tuck Under Parking	Wood Shear Wall	10%	90%		0%				CAN NOT SEE IN COURT	Y.
301 N CORTEEN PL	91607		2	Living Space	Wood Shear Wall	?	10%	?	?	REAR		Y		Y
2345 W MAGNOLIA BLVD	91607			Tuck Under Parking	Wood Shear Wall	0%	90%		20%	BALCONIE	S	PA	RKING, STAIRS & BALCON	I Y
1922 W BURBANK BLVD	91607		2	Tuck Under Parking	Wood Shear Wall	20%	90%	?	30%			PA	RKING, STAIRS & BALCON	Y
1936 W BURBANK BLVD	91607			Tuck Under Parking	Wood Shear Wall	0%	10%		90%	BALCONIE	S	PA	RKING, STAIRS & BALCON	I Y
1940 W BURBANK BLVD	91607		2	Tuck Under Parking	Wood Shear Wall	20%	90%	?		REAR				Y
1936 W WEDDINGTON ST	91607			Tuck Under Parking	Wood Shear Wall	40%	90%			LEFT SIDE		PA	RKING, STAIRS & BALCON	I Y
1839 W MAGNOLIA BLVD	91607		2	Tuck Under Parking	Wood Shear Wall	20%	90%	?	50%				CAN NOT SEE IN COURT	Y
1860 W CHANDLER BLVD	91607			Tuck Under Parking	Wood Shear Wall	10%	90%	20%		LEFT SIDE			CAN NOT SEE IN COURT	Y
309 N AGNES AVE	91607		3	Tuck Under Parking	Wood Shear Wall	50%	90%	?					CAN NOT SEE IN COURT	Y
1424 W KILLION ST	91601			Tuck Under Parking	Wood Shear Wall	90%	0%			BALCONIE	S			Y
050 N TUJUNGA AVE	91601		3	Tuck Under Parking	Wood Shear Wall	20%	90%	?	?	ALCONIE	S	PA	RKING, STAIRS & BALCON	I Y
2222 W MAGNOLIA BLVD	91607			Living Space	Wood Shear Wall	10%							NEEDS INSPECTION	?
2331 W RIVERSIDE DR	91607		2	Tuck Under Parking	Wood Shear Wall	10%	?	?	?	LEFT SIDE		Y		Y
2360 W RIVERSIDE DR	91607			Tuck Under Parking	Wood Shear Wall	10%	20%	50%	0%	T & BALCO	DNIES			Y
041 N WHITSETT AVE	91607		2	Tuck Under Parking	Wood Shear Wall	90%	?	30%	?			PA	RKING, STAIRS & BALCON	I Y
2729 W MOORPARK ST	91604			Tuck Under Parking	Wood Shear Wall					BALCONIE	S		NEEDS INSPECTION	?
321 N COLFAX AVE	91604		2	Tuck Under Parking	Wood Shear Wall	10%	90%	?	?	REAR			CAN NOT SEE IN COURT	Y
264 N LAUREL CANYON BLVD	91604			Tuck Under Parking	Wood Shear Wall	0%	90%	20%		ALCONIE	s		CAN NOT SEE IN COURT	Y
2915 W BLOOMFIELD ST	91604		2	Tuck Under Parking	Wood Shear Wall	0%	7	?	?					2



STEP 2 USE GOOGLE MAPS TO PERFORM ONLINE SURVEY



ADDRESS		11249 Mara St
ZIP CODE	91601	
YEAR BUILT	1963	
UNIT COUNT	8	
STORY COUNT		2
	FRONT	100
OPENING SIZE RATIO OF FIRST	BACK	90
FLOOR VS FLOORS ABOVE (%)	LEFT	30
	RIGHT	40
CANTILEVERED		Yes
COMMENTS/DESCRIPTIC	ON	Tuck Under Parking
POSSIBILE SOFT STORY	1	Yes



30,000 surveyed6,000 classified as "No"24,000 classified as "Possible"



STEP 3 CONDUCT SITE VISIT EVALUATION

24,000 buildings classified as "Possible soft-story" were evaluated and surveyed.

Soft-Story Evaluation Form DRAFT

Inspection:		
Inspector ID:		
Picture No.:	Inspection start time:	AM []
7		
Building Description:	Type of Construction:	Concrete Podium
Building of Interest: Corner Lot	Wood Frame	Concrete Shear Wall
Address:	Steel Frame	Unreinforced masonry
AKA Address:	Tilt-Up Concrete	Reinforced masonry
Zip Code: Council District #: Year Built:	Concrete Frame	Other:
Neighborhood:	Primary Occupancy:	
Number of Residential Units ≥ than 4:(Y/N)	Dwelling	Commercial Governmen
Number of stories above ground: below ground:	Other residential	Offices Historic
First Floor Use:	Public Assembly	Industrial School
	Emergency Services	Other:
Soft Story Determination: Opening Size Ratio of First Floor VS Floors Above (%):		
Front: Back: Left: Right:		
Cantilevered (> than 4 feet): (Y/N) Comments/Descri	iption:	
Possible Weak Story: (Y/N/?) ***If (?), explain ab	ove in Comments/Descri	iption***




SURVEY POSSIBLE SOFT-STORY BUILDINGS

8 AN DID OF WOOD I		Possibl	le Soft Story: YES
Building Description			
Type of Construction:	Wood Frame		
Building of Interest:			
AKA Address:	1 1		
Year Built:	1926	Zip Code:	90038
Neighborhood:		Council District:	13
No. of Building on Property:			
No. of Res Units Greater Than	4: YES		
No. of Stories:	3	Unit Count (LAHCID):	5
Primary Occupancy:	Dwelling		
First Floor Use:	Living Space,Par	king	
Soft Story Determination Opening Size Ratio of First Flo Front:	oor Vs Floors Above 10	(%): Back:	100
Opening Size Ratio of First Flo			100 30
Opening Size Ratio of First Flo Front: Left:	10 40 YES	Back:	30
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description:	10 40 YES Staircase Balcony left	Back: Right:	30
Opening Šize Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination	10 40 YES Staircase Balcony left	Back: Right:	30
Opening Šize Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination	10 40 YES Staircase Balcony left	Back: Right: y,Tuck Under Parking,TUP @ left-	30 -rear, cantalever 6' @ rear
Opening Šize Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%):	10 40 YES Staircase Balcony left NO	Back: Right: y,Tuck Under Parking,TUP @ left Turf Grass (> than 15%):	30 -rear, cantalever 6' @ rear
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs:	10 40 YES Staircase Balcony left NO Off	Back: Right: y,Tuck Under Parking,TUP @ left Turf Grass (> than 15%):	30 -rear, cantalever 6' @ rear
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection	10 40 YES Staircase Balcony left NO Off	Back: Right: y,Tuck Under Parking,TUP @ left Turf Grass (> than 15%): L	30 -rear, cantalever 6' @ rear
Opening Šize Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection Inspector's Name:	10 40 YES Staircase Balcony left NO Off Incandescent,CFI	Back: Right: y,Tuck Under Parking,TUP @ left Turf Grass (> than 15%):	30 .rear, cantalever 6' @ rear N
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection	10 40 YES Staircase Balcony left NO Off Incandescent,CFI	Back: Right: y,Tuck Under Parking,TUP @ left Turf Grass (> than 15%): L	30 .rear, cantalever 6' @ rear N

State Assembly District No:

BAS Parcel No:

218032









110 S CHRONDELET S			
Building Description			
Type of Construction:	Wood Frame		
AKA Address:			
Building of Interest:		Condo:	No
Year Built:	1954	Zip Code:	90057
Neighborhood:		Council District:	13
No. of Building on Property:		Street Unit:	
No. of Res Units Greater Than 4		AKA Street Unit:	
No. of Stories:	2	Unit Count (LAHCID):	6
Primary Occupancy:	Dwelling		
First Floor Use:	Living Space		
Opening Size Ratio of First Floo Front:	r Vs Floors Above 10 10	Back:	0
Soft Story Determination Opening Size Ratio of First Floor Front: Left: Cantillevered (>than 4 feet): Comments/Description:	10		-
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination	10 10 No	Back: Right:	0
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%):	10 10 No Yes	Back:	-
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights:	10 10 No	Back: Right:	0
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%):	10 10 No Yes	Back: Right:	0
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights:	10 10 No Yes Off	Back: Right:	0
Opening Size Ratio of First Floor Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection	10 10 No Yes Off	Back: Right:	0
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs:	10 10 No Yes Off LED	Back: Right: Turf Grass (> than 15%):	0 No
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection Inspector's Name:	10 10 No Yes Off LED	Back: Right: Turf Grass (> than 15%):	0 No
Opening Size Ratio of First Floor Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection Inspector's Name: Inspection Type:	10 10 No Yes Off LED	Back: Right: Turf Grass (> than 15%):	0 No
Opening Size Ratio of First Floo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection Inspector's Name:	10 10 No Yes Off LED C. MORENO	Back: Right: Turf Grass (> than 15%): Inspection Date:	0 No 11/20/2014





	-		
Building Description			
Type of Construction:	Wood Frame		
Building of Interest:			
AKA Address:			
Year Built:	1964	Zip Code:	90039
Neighborhood:		Council District:	13
No. of Building on Property:			
No. of Res Units Greater Than	4: YES		
No. of Stories:	2	Unit Count (LAHCID):	6
Primary Occupancy:	Dwelling		
First Floor Use:	Living Space,Parl	king	
Soft Story Determination Opening Size Ratio of First Flo			70
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet):	15 40 YES	Back: Right:	70 40
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description:	15 40 YES	Back:	
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination	15 40 YES Tuck Under Parki	Back: Right: ng,TUP @ rear & right	40
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%):	15 40 YES Tuck Under Parki NO	Back: Right:	
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights:	15 40 YES Tuck Under Parki NO Off	Back: Right: ng,TUP @ rear & right	40
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%):	15 40 YES Tuck Under Parki NO	Back: Right: ng,TUP @ rear & right	40
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights:	15 40 YES Tuck Under Parki NO Off	Back: Right: ng,TUP @ rear & right	40
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs:	15 40 YES Tuck Under Parki NO Off	Back: Right: ng,TUP @ rear & right	40
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection	15 40 YES Tuck Under Parki NO Off Incandescent	Back: Right: ing,TUP @ rear & right Turf Grass (> than 15%):	40 N
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection Inspector's Name: Inspection Type:	15 40 YES Tuck Under Parki NO Off Incandescent	Back: Right: ing,TUP @ rear & right Turf Grass (> than 15%):	40 N
Opening Size Ratio of First Flo Front: Left: Cantillevered (>than 4 feet): Comments/Description: Sustainability Determination Landscaping (> than 15%): Status of Exterior Lights: Type of Light Bulbs: Inspection Inspector's Name:	15 40 YES Tuck Under Parki NO Off Incandescent G. ZUBER	Back: Right: ing,TUP @ rear & right Turf Grass (> than 15%): Inspection Date:	40 N 11/22/2014









STEP 4 COMPLIE FINAL LIST OF SOFT-STORY WOOD BUILDINGS

- There are **13,500** currently identified as wood soft-story buildings in the City of Los Angeles
- 78% are 2 stories or more
- 22% are 3 stories or more
- 99% are apartments/condos

	LA	P	D	BS
D	EPARTMENT	OF BUILDIN	IG AND	SAFETY

DRAFT ONLY - NOT FOR PUBLIC DISSEMINATION DEPARTMENT OF BUILDING AND SAFETY WOOD SOFT STORY BUILDING INVENTORY Page 1 of 397 August 24, 2015

Number of Buildings = 13,472

Numb	er of Buildings = 13,4/2			
CD	Address	ZIP	APN	# of Stories
1	1629 W 11TH PL	90015	5137019025	2
1	1663 W 11TH PL	90015	5137019018	2
1	1863 W 11TH PL	90006	5136020002	2
1	1652 W 12TH ST	90015	5137028001	2
1	2380 W 12TH ST	90006	5076017001	3
1	2692 W 12TH ST	90006	5078033022	2
1	2772 W 12TH ST	90006	5078035026	2
1	2229 W 14TH ST	90006	5056004013	2
1	2205 W 15TH ST	90006	5056005006	2
1	2214 W 15TH ST	80008	5056006007	2
1	2241 W 15TH ST	90006	5056005020	3
1	2255 W 15TH ST	90006	5056005022	2
1	1035 W 17TH ST	90015	5135024006	2
1	1044 W 17TH ST	90015	5135025010	2
1	1112 W 18TH ST	90015	5135015016	2
1	1116 W 18TH ST	90015	5135015015	2
1	1423 W 20TH ST	90007	5056026020	2
1	1750 W 20TH ST	90007	5075039032	2
1	1858 W 20TH ST	90007	5075030005	2
1	1862 W 20TH ST	90007	5075030006	2
1	925 W 21ST ST	90007	5124015004	2
1	635 W 23RD ST	90007	5124032003	2
1	850 W 23RD ST	90007	5124023001	2
1	1023 W 23RD ST	90007	5124006007	2
1	1025 W 23RD ST	90007	5124006006	2
1	1008 W 24TH ST	90007	5124008021	3
1	1016 W 24TH ST	90007	5124008020	3
1	1024 W 24TH ST	90007	5124008018	3
1	1814 W 4TH ST	90057	5154023011	2
1	1817 W 4TH ST	90057	5154022001	2
1	1818 W 4TH ST	90057	5154023010	2
1	2503 W 4TH ST	90057	5155032001	2
1	1135 W 7TH ST	90017	5143021016	2
1	825 W ADAMS BLVD	90007	5124024009	3





ESTABLISH RETROFIT CRITERIA

Strengthen soft, weak or open wall line **ONLY** :

- <u>The Design Base Shear</u>
 - 75% of current requirement under ASCE 7
- Story Drift Limitations
 - Not to exceed 0.025 times the story height

Exception

Buildings greater than 2 stories with horizontal structural irregularities shall meet the additional requirements under ASCE 7, for the entire story with weak or open wall lines.



STEP 6

ESTABLISH ORDINANCE

DRAFT ONLY – NOT FOR PUBLIC DISSEMINATION ATTORNEY WORK PRODUCT PRIVILEGED AND CONFIDENTIAL

MANDATORY EARTHQUAKE HAZARD REDUCTION IN EXISTING WOOD FRAME BUILDINGS WITH SOFT, WEAK OR OPEN-FRONT WALLS Ordinance No. ________. Fifercive ________

I. PURPOSE

The purpose of this division is to promote public welfare and safety by reducing the risk of death or injury that may result from the effects of earthquakes on existing wood-frame multi-unit buildings with soft, weak or open front walls. In the Northridge Earthquake, many multi-story wood-frame buildings with tuck-under parking performed poorly and collapsed, causing the loss of human life, personal injury, and property damage. It has been determined that the structural vulnerability of this building type is typically due to soft, weak, or open front walls. This division creates minimum standards to mitigate hazards from these deficiencies. Adherence to these minimum standards will improve the performance of these buildings, but will not necessarily prevent the loss of life, injury, or all earthquake-related damage.

This division shall not require existing electrical, plumbing, mechanical or fire-safety systems to be altered unless they constitute a hazard to life or property. Nor shall this division require compliance for any other violations under Los Angeles Municipal Code unless they constitute a hazard to life or property. Notwithstanding the scope of this division, its provisions shall not be interpreted to waive any limitations or requirements imposed by other statutes or ordinances of the state or City.

Unless expressly stated herein, this division shall not amend, repeal, or supersede provisions of the Los Angeles Municipal Code. When the requirements of this division are not identical to or are in conflict with the requirements of any other part of the Los Angeles Municipal Code, the most restrictive requirement prescribing greater safety to person, property, or public welfare shall prevail.

II. SCOPE

The provisions of this division shall apply to all existing buildings of wood-frame construction, or wood-frame portions thereof, where:

 A permit for construction of a new building was applied for before January 1, 1978, or, if no permit can be located, the structure is determined by the Department to have been built before January 1, 1980; and

Page 1 of 8

Wood Soft-Story Retrofit Ordinance 2015.07.02

DRAFT ONLY – NOT FOR PUBLIC DISSEMINATION ATTORNEY WORK PRODUCT PRIVILEGED AND CONFIDENTIAL

The ground floor portion of the structure contains parking or other similar open floor space that causes soft, weak or open-front wall lines, and there exists one or more stories above.

EXCEPTION: This division shall not apply to any building containing 3 dwelling units or less if the building is used solely for residential purposes.

III. DEFINITIONS

In addition to the definitions in Division 2 of this Code, the following definitions shall apply for the purposes of this division:

CRIPPLE WALL is a wood-framed stud wall extending from the top of the foundation wall to the underside of the lowest floor framing of the building.

DWELLING UNIT shall include any individual residential unit within either an R-1 or R-2 occupancy building, including a mixed-occupancy building when part of it is either an R-1 or R-2 occupancy. A dwelling unit shall include the area of a building that is occupied as a dwelling unit, whether the building is approved or unapproved for residential use.

GROUND FLOOR is any floor within the wood frame portion of a building whose elevation is immediately accessible from an adjacent grade by vehicles or pedestrians. The ground floor portion of the structure does not include any floor that is completely below adjacent grades.

OPEN-FRONT WALL LINE is an exterior wall line, without vertical elements of the lateral force-resisting system, which requires tributary seismic forces to be resisted by diaphragm rotation or excessive cantilever beyond parallel lines of shear walls. Diaphragms that cantilever more than 25 percent of the distance between lines of lateral force resisting elements from which the diaphragm cantilevers shall be considered excessive. Exterior exit balconies of six feet or less in width shall not be considered excessive cantilevers.

QUALIFIED HISTORICAL BUILDING is any building designated or currently in the process of being designated as a "qualified historical building" as defined in Part 8, Title 24 of the California Code of Regulations.

RETROFIT is an improvement of the lateral force-resisting system by alteration of existing structural elements or addition of new structural elements.

Page 2 of 8

Wood Soft-Story Retrofit Ordinance 2015.07.02



STEP 7 NOTIFY BUILDING OWNERS


- Where to obtain help
- Ordinance description
- Timeline for compliance
- Webpage for guidance

PRES	SIONERS 	CITY OF LOS ANGELE CALIFORNA ENLIFORMA ENC. CARGETT MAYOR	S BUILDING HAND DARETY Lives of the second s
		NOTIFICATION	
building(s Ordinance with Soft This Ord following: I. II.	e #(Mand Weak or Open From inance shall apply Wood frame cons Built and issued a	w that the Department of Building a meet the criteria for mandatory fattory Earthquek Haraar Reduction at Walls), otherwise known as the Sof to all existing commercial and resid truction with two or more stories; . Certificate of Occupancy before Janu	compliance with seismic retrofit n Exiting Wood Frame Buildings t-Story Retrofit Program. lential buildings having all of the arry 1, 1980; and
III.		king or other similar open floor spa	ce that causes soft, weak or open
		sent out in the near future warranting a guidance and information regarding th	
660.85, 85 ⁻² (R	av. 04 21/2015) AN	I EQUAL EMPLOYMENT OPPORTUNITY - AFFI	RMATIVE ACTION EMPLOYER



STEP 8 ISSUE TECHNICAL RETROFIT BULLETIN FOR CONSTRUCTION PROFESSIONALS

- Structural Design
 - Prescriptive
 - Alternative Methods
- Permitting Process
 - Required submittal package



LA DBSINFORMATION BULLETIN / PUBLIC - BUILDING CODE Effective DOCUMENT NO.: P/BC 2014-XXX

As a covered entity under Title II of the Americans with Disabilities Act, the Oity of Los Angeles does not discriminate on the basis of disability and, upon request, will por reasonable accommodation to ensure equal access to its programs, services and activities. For efficient handing of information intentity and in the intent, conversion to new format of code intelest and administrative information buildins including MOD and RAA, the wee pervicuous fusade will allow fiscibility and itimity distributi new format of code related and ad information to the public. Page 1 of 5



Revised:

STEP 9 SEND ORDER TO COMPLY

- Compliance requirements
- Compliance timeline
- Appeal procedures


BUILDING AND SAFETY COMMISSIONERS VAN AMBATIELOS PREDONT E. FELICIA BRANNON VICE PREDIDIT JOSELYN GEAGAROSENTHAL GEORGE HOVAGUIMIAN JAVIER MUNEZ	CITY OF LOS ANGELES CALIFORNIA ERIC GARCETTI MAYOR	BUILDING AND SAFETY BI LOTH FULGER STREET LOST FULGER STREET RAYMOND S. CHAN, C.E., S.E. GRIEBAL, MANGER FRANK BUSH EXECUTIVE OFFICER
	ORDER TO COMPLY	
OWNER ADDRESS CITY ZIP PHONE #	c	CASE #: EFFECTIVE DATE: OMPLIANCEDATE:
building(s) onsite have b for mandatory complian	e address referenced above and a review of depr been determined by the Department of Building a ce with seismic retrofit Ordinance # 'ood Frame Buildings with Soft, Weak or Open	and Safety to be within the scope [Mandatory Earthquake Hazard
In addition, the building compliance:	g(s) onsite have been recognized with the fol	lowing priority designation for
I. Residential b II. All other bui	uildings with 16 or more dwelling units and/or 3 Idings	or more stories
Therefore, you are hereby	y ordered to comply with the following requirem	ents.
1. Within 365 d	days (1 year) of the effective date of this order,	
Ordinan b. Submit a the minir	proof of seismic retrofit which meets the : ce, or a structural analysis and plans to seismically retr num requirements of this Ordinance, or slans for the demolition of the building	
retrofit or de 3. Within 1,460	days (2 years) of the effective date of this order molition. 0 days (4 years) of the effective date of this or essary permits.	
NOTE: A CERTIFIC	ATE HAS BEEN FILED WITH THE COUNTY	RECORDERS NOTING THAT

NOTE: A CERTIFICATE HAS BEEN FILED WITH THE COUNTY RECORDERS NOTING THAT THE BUILDING(S) IS (ARE) WITHIN THE SCOPE OF THE MANDATORY RETROFIT ORDINANCE. The certificate shall also state that the owner thereof has been ordered to structurally analyze the building(s) and to structurally alter or demolish it (then) when the Department determines the building(s) is (are) not in compliance to the ordinance.

6588.351 (Rev. 52211) AN EQUAL EMPLOYMENT OPPORTUNITY - AFFIRMATIVE ACTION EMPLOYER Page 1 of 2



TIME LIMIT FOR RETROFIT





STEP 10

MAKE THE PROGRAM COST RECOVERY TO SUPPORT A SPECIAL PLAN CHECK AND INSPECTION TEAM

13,500 projects at
\$665 of average plan check and permit fees,
\$9 million total revenue for the 4-year program

\$2.25 million per year to support a special plan check and inspection team

Cost will be recovered.



QUESTIONS AND COMMENTS

For further information, please contact Catherine Nuezca Gaba

Chief of Wood Frame Soft-story Program (213) 482-0435 or Catherine.NuezcaGaba@lacity.org

