

# 2006 International Fire Code Errata

FIRST PRINTING (Updated July 1, 2006)
---------------------------------------

## CHAPTER 6 BUILDING SERVICES AND SYSTEMS

*Section 603.6.1 should read as follows:*

**603.6.1 Masonry chimneys.** Masonry chimneys that, upon inspection, are found to be without a flue liner and that have open mortar joints which will permit smoke or gases to be discharged into the building, or which are cracked as to be dangerous, shall be repaired or relined with a listed chimney liner system installed in accordance with the manufacturer's installation instructions or a flue lining system installed in accordance with the requirements of the *International Building Code* and appropriate for the intended class of chimney service. *(posted 7-10-06)*