2006 International Residential Code Errata

(Portions of text and tables not shown are affected by the errata)

CHAPTER 3
BUILDING PLANNING

R301.2.2.3.2 Masonry construction. Masonry construction shall comply with the requirements of Section 606.~~11.2~~. 12.2

CHAPTER 8
ROOF-CEILING CONSTRUCTION

TABLE 804.3.1(1) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(2) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(3) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(4) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(5) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(6) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(7) Last row, first column….1000S162-97 should be 1200S162-97

TABLE 804.3.1(8) Last row, first column….1000S162-97 should be 1200S162-97

Appendix H
PATIO COVERS

AH105.1 General….shall be provided with exits conforming to the provisions of Section ~~R310~~ R311 of this code.

INDEX

JOINTS, PIPE

2006 International Residential Code Errata

<small>(Portions of text and tables not shown are affected by the errata)</small>

INDEX