## 2007/2008 ICC PERFORMANCE CODE HEARING RESULTS

## PC1-07/08

This code change was heard by the IBC Structural Code Development Committee.

Committee Action: Disapproved

**Committee Reason:** While the proposal may provide useful guidance with respect to flood events, it seems to be mostly commentary. Furthermore, requirements for specific events such as floods would be incorrectly placed under this general section of the performance code as this proposal was written.

Assembly Action: None

## PC2-07/08

This code change was heard by the IBC General Code Development Committee.

Committee Action: Disapproved

**Committee Reason:** The ICCPC intentionally does not reference standards directly but depends upon Section 104 dealing with "Approved Methods" to allow the application of specific codes and standards and a variety of engineering methods.

Assembly Action: None