

# 2006 International Mechanical Code Errata

THIRD PRINTING (UPDATED May, 2008)

## CHAPTER 6

**Section 602.2.1** Materials ~~exposed~~ within plenums.

**Section 603.17.2** Prohibited locations.

Third line ... extension within toilet and bathing rooms ~~floors~~ required by the ...

# 2006 International Mechanical Code Errata

FIRST PRINTING (UPDATED May, 2008)

## CHAPTER 6

**602.2.1.5.2 Approval.** The foam plastic insulation shall be covered on tests conducted in accordance with Section 2603.89 of the *International Building Code*.

### **603.6 Flexible air ducts and flexible air connectors.**

**Last line** ...Sections 6063.6.2 through 603.6.4.

### **607.5.2 Fire barriers.**

**Last line 2 lines** ...104920.1.2 and 102021.5, respectively, of the *International Building Code*.

### **607.6.1 Through penetrations.**

**Last line 2 lines** ...openings, see Exception 7 to Section 7027.2 of the *International Building Code*.

#### **607.6.2.1 Ceiling radiation dampers.**

**Item 2, second line** ...accordance with Section 712.4.1.2 of the ...