

2006 International Mechanical Code Errata

THIRD PRINTING (UPDATED May, 2008)

CHAPTER 3

Section 301.4 Listed and labeled.

Exception: Listing and labeling of equipment and appliances used ...

2006 International Mechanical Code Errata

THIRD PRINTING (UPDATED May, 2008)

CHAPTER 4

Section 401.4.3 Flood Hazard.

For structures located in flood hazard areas, outdoor exhaust and air intake openings shall be at or above the design flood elevation.

2006 International Mechanical Code Errata

THIRD PRINTING (UPDATED May, 2008)

CHAPTER 6

Section 602.2.1 Materials ~~exposed~~ within plenums.

Section 603.17.2 Prohibited locations.

Third line ... extension within toilet and bathing rooms ~~floors~~ required by the ...

2006 International Mechanical Code Errata

THIRD PRINTING (UPDATED May, 2008)

CHAPTER 8

Section 805.2 Solid fuel appliances.

There should be only one exception; the second exception should be text following the exception rather than a second exception, as follows:

Factory-built chimneys installed in dwelling units with solid fuel-burning appliances shall comply with the Type HT requirements of UL 103 and shall be marked "Type HT" and "Residential Type and Building Heating Appliance Chimney".

Exceptions:

4. Chimneys for use with open combustion chamber fireplaces shall comply with the requirements of UL 103 and shall be marked "Residential Type and Building Heating Appliance Chimney".

~~2. Chimneys for use with open combustion chamber appliances installed in buildings other than dwelling units shall comply with the requirements of UL 103 and shall be marked "Building Heating Appliance Chimney" or "Residential Type and Building Heating Appliance Chimney".~~

Chimneys for use with open combustion chamber appliances installed in buildings other than dwelling units shall comply with the requirements of UL 103 and shall be marked "Building Heating Appliance Chimney" or "Residential Type and Building Heating Appliance Chimney".

2006 International Mechanical Code Errata

FIRST PRINTING (UPDATED May, 2008)

CHAPTER 3

301.4 Listed and labeled.

Exception: Listing and labeling of equipment and ~~applications~~ appliances used for refrigeration

2006 International Mechanical Code Errata

FIRST PRINTING (UPDATED May, 2008)

CHAPTER 4

Table 403.3 Required outdoor ventilation air.

Public spaces

Smoking lounges ^{b,h,g}

2006 International Mechanical Code Errata

FIRST PRINTING (UPDATED May, 2008)

CHAPTER 5

501.2.1 Location of exhaust outlets.

Item 4. For specific systems: For clothes dryer exhaust, see Section 504.4; for kitchen hoods, see Section 506.3; for dust, stock and conveying systems, see Section 511.2; and for subslab soil exhaust systems, see Section 512.4.

506.3.3.1 Grease duct test is renumbered as **Section 506.3.2.5.**

506.3.3 Grease duct supports.

Delete last paragraph as follows:

~~A test shall be performed for the entire duct system including the hood to duct transition connection. The ductwork shall be permitted to be tested in sections, provided that every joint is tested.~~

2006 International Mechanical Code Errata

FIRST PRINTING (UPDATED May, 2008)

CHAPTER 6

602.2.1.5.2 Approval. The foam plastic insulation shall be covered on tests conducted in accordance with Section 2603.89 of the *International Building Code*.

603.6 Flexible air ducts and flexible air connectors.

Last line ...Sections 6063.6.2 through 603.6.4.

607.5.2 Fire barriers.

Last line 2 lines ...104920.1.2 and 102021.5, respectively, of the *International Building Code*.

607.6.1 Through penetrations.

Last line 2 lines ...openings, see Exception 7 to Section 7027.2 of the *International Building Code*.

607.6.2.1 Ceiling radiation dampers.

Item 2, second line ...accordance with Section 712.4.1.2 of the ...