

# 2006 International Residential Code Study Companion

## Errata

Study Session 5, page 112, lower right illustration should indicate “Interior” rather than “Exterior.” (posted 11/21/09)

Study Session 9, page 218, illustration should indicate that minimum clearance from the back of a masonry fireplace to combustibles is 4 inches, not 2 inches. (posted 11/21/09)

Study Session 9, page 221, illustration should indicate that 3-foot minimum measurement is taken from the highest point of chimney penetration of the roof, not the lowest point. (posted 11/21/09)