2006 International Building Code Study Companion

Errata to the First and Second Printings

Study Session 2, page 39, 311.1. <u>Dairy Daily products</u> (posted 5/1/07)

Study Session 5, page 129, 704.8. **Given:** A nonsprinklered building of Type VA construction. The 1-hour exterior wall shown is located <u>12</u> 8 feet from an interior lot line. It has protected openings as shown. (posted 5/14/07)

Answer Key, page 504, #8. Sec. 1008.1.3.1, #2 #4. (posted 6/15/07)

Answer Key, page 510, #2. Table 1607.1, #4, #35 (posted 6/26/07)

Answer Key, page 510, add #29. b Sec. 2304.12, Exc. (posted 6/26/07)

Study Session 17, page 453, Title of figure. <u>Surrounding materials</u> Attic access opening (posted 6/26/07)

Study Session 2, page 53, #4. c. 1-hour fire barrier <u>and/</u>or horizontal assembly (posted 8/4/07).

Study Session 7, page 193, #13. d. a single horizontal exit door installed in a smoke partition (posted 12/17/09).