## 2006 International Residential Code Errata

(Portions of text and tables not shown are affected by the errata)

## 1<sup>st</sup> through 6<sup>th</sup> PRINTING (Posted 06-06-2012)

### CHAPTER 3 BUILDING PLANNING

R301.2.2.3.2 Masonry construction. Masonry construction shall comply with the requirements of Section 606.11.2. 12.2

### CHAPTER 8 ROOF-CEILING CONSTRUCTION

TABLE 804.3.1(1) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(2) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(3) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(4) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(5) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(6) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(7) Last row, first column....1000S162-97 should be 1200S162-97

TABLE 804.3.1(8) Last row, first column....1000S162-97 should be 1200S162-97

#### Appendix H PATIO COVERS

AH105.1 General....shall be provided with exits conforming to the provisions of Section R310 R311 of this code.

#### INDEX

JOINTS, PIPE

Slip......<u>P3003.3.7</u> <u>P2704.1</u>

# 2006 International Residential Code Errata

(Portions of text and tables not shown are affected by the errata)

1<sup>st</sup> through 6<sup>th</sup> PRINTING (July 25, 2011)

## APPENDIX H PATIO COVER

AH105.1 General....shall be provided with exits conforming to the provisions of Section R310 R311 of this code.