

# 2009 International Building Code Study Companion

## Errata

Study Session 7, page 196, #13. d. a single ~~horizontal exit~~ door installed in a smoke partition (posted 12/17/09).

Study Session 2, page 508, # 32 and 33. Correct references for questions to be Table 508.4, not ~~508.3.3~~. (posted 10/11/10).

Study Session 5 Answer Key, Page 511, #27 reference section only. Correct reference is Sec. 705.2.3 (posted 11/3/2014).

Study Session 6 Answer Key, Page 512, #10 reference section only. Correct reference is Sec. 707.5.1, Exc. 3 (posted 11/3/2014).

Study Session 15 Answer Key, Page 521, #30 reference section only. Correct reference is Sec. 1804.3 (posted 11/3/2014).