

**2009 INTERNATIONAL ENERGY
CONSERVATION CODE ERRATA**

1st through 4th PRINTING (Updated July 6, 2010)

INDEX

H

HOT BYPASS.....503.4.7

(Add HOT BYPASS after HISTORIC BUILDINGS, under H in the Index)

INDEX

M

~~MOISTURE CONTROL.....402.5~~

(Remove Moisture Control from the Index) Posted 1/28/2010

P

POOL COVERS.....403.9.3, 504.7.3

(Add 403.9.3 to the Section area of Pool Covers in the Index) Posted 1/28/2010

INDEX

P

PARALLEL PATH CALCULATION.....~~402.2.4~~ 402.2.5

(In the Index, Parallel Path Calculation refers to Section 402.2.4, this should be changed to Section 402.2.5) Posted 5/14/2009

V

VAPOR RETARDER.....402.2.9

 Defined.....~~202~~

(In the Index, Defined should be removed from under Vapor Retarder) Posted 5/14/2009