

2012 International Fire Code Errata

(Portions of text and tables not shown are unaffected by the errata)

1st PRINTING (Posted: 8-30-12)

CHAPTER 10 MEANS OF EGRESS

1007.5 Platform lifts. Platform (wheelchair) lifts shall not serve as part of an accessible means of egress, except where allowed as part of a required accessible route in Section 1109.7-1109.8, Items 1 through 9. Standby power shall be provided in accordance with Chapter 27 for platform lifts permitted to serve as part of a means of egress.

**Table 1014.3
COMMON PATH OF EGRESS TRAVEL**

Occupancy	Without Sprinkler System (feet)		With Sprinkler System (feet)
	Occupant Load		
	<= 30	> 30	
All others ^{c,1}	75	75	75 ^{a,b}

(Remainder of table unchanged)

**Table 1016.2
EXIT ACCESS TRAVEL DISTANCE ^a**

Occupancy	Without Sprinkler System (feet)	With Sprinkler System (feet)
I-1	Not Permitted	250 ^{e,b}

(Remainder of table unchanged)

1028.12 Seat stability. In a building, room or space used for assembly purposes, the seats shall be securely fastened to the floor.

Exceptions:

1. In a building, room or space used for assembly purposes or portions thereof without ramped or tiered floors for seating and with 200 or fewer seats, the seats shall not be required to be fastened to the floor.
2. In a building, room or space used for assembly purposes or portions thereof with seating at tables and without ramped or tiered floors for seating, the seats shall not be required to be fastened to the floor.
3. through 6. (No change)