



**2021 – 2022 ICC CODE DEVELOPMENT CYCLE  
UPDATES TO THE 2021 REPORT OF THE COMMITTEE  
ACTION HEARINGS  
TO THE INTERNATIONAL CODES  
GROUP A**

The following is a compilation of errata discovered since the posting of the Report of the Committee Action Hearing results on May 24, 2021

**Updated 6/7/2021**  
**Updated 6/17/2021**

2021-2022 Code Development Cycle, Group A (2021) Report of the Committee Action Hearing to the 2021 *International Codes*

First Printing

Publication Date: June 2021

Copyright © 2021

by

International Code Council, Inc.

ALL RIGHTS RESERVED. This 2021-2022 Code Development Cycle, Group A (2021) Report of the Committee Action Hearing to the 2021 *International Codes* is a copyrighted work owned by the International Code Council, Inc. ("ICC"). Without advance written permission from the ICC, no part of this book may be reproduced, distributed, or transmitted in any form or by any means, including, without limitations, electronic, optical or mechanical means (by way of example and not limitation, photocopying, or recording by or in an information storage retrieval system). For information on use rights and permissions, please contact: ICC Publications, 4051 Flossmoor Road, Country Club Hills IL, 60478. Phone 1-888-ICC-SAFE (422-7233).

Trademarks: "International Code Council," the "International Code Council" logo, "ICC," the "ICC" logo and other names and trademarks appearing in this book are registered trademarks of the International Code Council, Inc., and/or its licensors (as applicable), and may not be used without permission.

PRINTED IN THE U.S.A.

# INTERNATIONAL BUILDING CODE – MEANS OF EGRESS

Updated 6-17-21

E149-21: Replace the Committee reason with the following

## E149-21

**Committee Action:**

**As Submitted**

**Committee Reason:** This proposal was approved as it clarifies that captioning applies to both prerecorded and real time information. (14-0)

---

# INTERNATIONAL FIRE CODE

F12-21: Correction to the Committee reason

## F12-21

Committee Action:

Disapproved

**Committee Reason:** The committee stated that the reasons for disapproval were the specifics of this section are for hazardous locations and by adding in criteria that is just generic is inappropriate for this to go in this location and in addition the current referenced standard NFPA 505 lists **NFPA UL 583 and NFPA UL 558** as reference standards within it so it would be redundant to add them. (Vote: 12-1).

---

## INTERNATIONAL MECHANICAL CODE

M11-21: Withdrawn result did not appear in the Report of Committee Action results

### **M11-21**

Committee Action:

Withdrawn

M11-21

---