

202

Errata: IMC Chapter: 2

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 202

Posted: March 6, 2019

Correction:

Page 15, replace the definition of LOW-PROBABILITY PUMP as follows: "A pump that is designed to prevent atmospheric release of the pumped fluid by one of the following methods: 1. The pump is permanently sealed. 2. The pump incorporates a static seal. 3. The pump incorporates not less than two sequential dynamic shaft seals to isolate the pumped fluid from atmosphere at shaft penetrations and automatically shuts down upon failure of any seal."

Correlation Notes: None

[F] 502.4

Errata: IMC Chapter: 5

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: [F] 502.4

Posted: March 6, 2019

Correction:

Page 42, Section [F] 502.4 should read as follows: “Stationary storage battery systems shall be regulated and ventilated in accordance with Section 1206.2.11.3 of the *International Fire Code* and the general requirements of this chapter.”

Correlation Notes: None

502.4.1

Errata: IMC Chapter: 5

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: [F] 502.4.1

Posted: March 6, 2019

Correction:

Section 502.4.1 is deleted.

Correlation Notes: None

502.4.2

Errata: IMC Chapter: 5

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: [F] 502.4.2

Posted: March 6, 2019

Correction:

Section 502.4.2 is deleted.

Correlation Notes: None

502.4.3

Errata: IMC Chapter: 5

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: [F] 502.4.3

Posted: March 6, 2019

Correction:

Section 502.4.3 is deleted.

Correlation Notes: None

[F] 502.5

Errata: IMC Chapter: 5

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: [F] 502.5

Posted: March 6, 2019

Correction:

Section [F] 502.5 should read as follows: "Stationary storage battery systems installed in cabinets shall be provided with ventilation in accordance with Section 502.4."

Correlation Notes: None

506.3.11.1

Errata: IMC Chapter: 5

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 506.3.11.1

Posted: March 6, 2019

Correction:

Page 54, Section 506.3.11.1, the metric conversion for 6 inches should be "(152 mm)."

Correlation Notes: None

805.3

Errata: IMC Chapter: 8

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 805.3

Posted: March 6, 2019

Correction:

Page 88, Insert Section 805.3 as follows and renumber subsequent sections: "805.3 Factory-built fireplaces. Chimneys for use with factory-built fireplaces shall comply with the requirements of UL 127."

Correlation Notes: None

1102.2.2.3

Errata: IMC Chapter: 11
--

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 1102.2.2.3

Posted: March 6, 2019

Correction:

Page 100, Section 1102.2.2.3, both references to “ARI 700” should be “AHRI 700.”

Correlation Notes: None

1103.1

Errata: IMC Chapter: 11
--

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 1103.1

Posted: March 6, 2019

Correction:

Page 103, Table 1103.1, the entry in the last column for row R-423A refrigerant should read as follows:
2-0-0^b

Correlation Notes: None

1106.5.3

Errata: IMC Chapter: 11
--

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 1106.5.3

Posted: March 6, 2019

Correction:

Page 109, Section 1106.5.3 should have a margin bar beside it.

Correlation Notes: None

1402.8.3

Errata: IMC Chapter: 14
--

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: 1402.8.3

Posted: March 6, 2019

Correction:

Page 126, Section 1402.8.3, the reference to "Chapter 10" should be "Chapter 12."

Correlation Notes: None

ACCA

Errata: IMC Chapter: 15
--

Code/Standard: International Mechanical Code

Applies to following Printings: 1st printing

Section/Table/Figure Number: ACCA

Posted: March 6, 2019

Correction:

Page 129, the first entry under ACCA should read as follows: "ANSI/ACCA 1 Manual D---2016: Residential duct systems."

Correlation Notes: None

SMACNA

Errata	2018 IMC Chapter 15
---------------	----------------------------

Code/Standard: 2018 International Mechanical Code
Applies to following Printings: 3rd, 2nd and 1st printing
Section/Table/Figure Number: SMACNA
Posted: Updated August 26, 2022

SMACNA

Sheet Metal & Air-Conditioning Contractors National Assoc., Inc.
4201 Lafayette Center Drive
ChantillyVA20151-120

SMACNA-~~40~~ 03 Fibrous Glass Duct Construction Standards 7th edition

SMACNA/ANSI—~~2016~~2005: HVAC Duct Construction Standards—Metal and Flexible, ~~4th~~ 3rd Edition (ANSI)

Correlation Notes: None.