

ERRATA TO THE 1997 UNIFORM BUILDING CODE

JANUARY 2001

Update your edition of the *Uniform Building Code*TM by correcting the items identified below.

VOLUME 1

- 1-6 **Table 1-A.** In the eighth row, revise “3.65 for each” to read “3.15 for each.”
- 1-17 **Sec. 305.2.3, Item 3.3.** In the fourth sentence, revise the reference code section to read “Section 1004.3.4.3.2” instead of Section 1005.”
- 1-23 **Sec. 307.11.3, Exception 3.** Replace the reference to “Ordinary Hazard Group 3” with “Ordinary Hazard Group 2.”
- 1-34 **Table 3-B.** In the row for H-1, revise the reference code section to read “Section 307.2.8” instead of “Section 307.2.9.”
- 1-49 **Sec. 418.** Delete title “FALLOUT SHELTERS” and replace with “RESERVED.” Delete the first sentence in this section.
- 1-61 **Sec. 601.1.** Revise the reference code section for open parking structures to read “Section 311” instead of “Section 405.”
- 1-66 **Table 6-A, Footnote 3.** Add “Sections 309.6 and 311.6.”
- 1-75 **Sec. 713.11.** In the last paragraph, revise “(27.8°C)” to read “(10°C).”
- 1-91 **Sec. 803(2).** In the first sentence, revise “paragraph 1” to read “item 1.”
- 1-99 **Sec. 905.7.5.** In the last sentence, revise “Part III” to read “Part IV.”
- 1-106 **Sec. 1003.2.3.2.** In the second paragraph, revise “may be divided” to read “shall be divided.”
- 1-106 **Sec. 1003.2.3.3, Exception.** Add “inches per person” at the end of the first sentence.
- 1-106 **Sec. 1003.2.3.4.** In the second paragraph, revise “Where an exit” to read “Where an exit enclosure.”
- 1-112 **Sec. 1004.2.4, Exception.** Revise the first sentence to read: “the separation distance determined in accordance with this section may be measured along a direct path of exit travel within a fire-resistive corridor complying with Section 1004.3.4.3.1 serving exit enclosures.”
- 1-112 **Sec. 1004.2.5.2.3.** In the first sentence, add “fire-resistive” after “exit occurs within a.”
- 1-118 **Sec. 1006.1.** In the second sentence, delete “and yards.”
- 1-118 **Sec. 1006.2.1.** Revise the second sentence to read: “The exit discharge shall not reenter the exit access.”
- 1-121 **Sec. 1007.4.2.** Delete the entire section and replace as follows:
1007.4.2 Travel distance. The maximum travel distance shall be as specified in Section 1004.2.5 with the applicable additional limitations of Section 1007.4.2.1. The travel distance in Section 1004.2.5 is permitted to be increased as specified in Section 1004.2.5.2.3.
- 1-121 **Sec. 1007.4.2.1 Travel within rooms.** Within Group H, Division 1, 2 and 3 Occupancies, all portions of any room shall be within 75 feet (22 850 mm) of an exit or exit access door from the room.
Within Group H, Division 7 and within fabrication areas of Group H, Division 6 Occupancies, the distance of travel to an exit corridor or to an exit shall not exceed 100 feet (30 480 mm).
- 1-121 **Sec. 1007.5.1.** In the first sentence, replace “that” with “width.”
- 1-122 **Sec. 1007.7.3.2.** In the first sentence, insert the word “the” between “of” and “refrigerated.”
- 1-136 **Sec. 1202.2.7.** In the first sentence, revise “(0.71 L/S/m²)” to read “(0.761 L/S/m²).”
- 1-142 **Sec. 1403.6.2.** In the first paragraph, revise the reference code section to read “Section 2307” instead of “Section 2316.”
- 1-159 **Sec. 1611.7.** In the last sentence, revise the reference code section to read “Section 1613” instead of “Section 1615.”
- 1-174 **Sec. 1809.5.1.** In the first sentence, revise the reference code section to read “Section 1605” instead of “Section 1603.”
- 1-175 **Table 18-I-A.** Revise the units in the third column title to read as follows: “LBS./SQ. FT./FT.”
- 1-181 **Sec. 1903.11.** In the first sentence, insert “P.C.I.” before “Manual 128.”
- 1-218 **Sec. 2320.8.6.** In the first sentence, add “(Section 4.4.1.2 of NDS-91)” after “Part I.”
- 1-261 **Sec. 2502 (24).** Correct the spelling of “Specificaton” to “Specification.”
- 1-304 **Sec. 3502, Part III, Chapter 22.** Revise the Section Reference for Structural Applications of Steel Cables for Buildings to read “Chapter 22, Div. XI” instead of “Chapter 22, Div. X.”
- 1-306 **Sec. 3504, Part IV, Chapter 22.** Revise the Section Reference for Structural Rivet Steel to read “Section 2202.3” instead of “Section 2202.1.” Also revise the Section Reference for Specifications for the Design of Cold-formed Stainless Steel Structural Members to read “Section 2202.2” instead of “Section 2202.1.”
- 1-327 **Sec. 1207.4.** In the second sentence of the third paragraph, revise “Mechanical Code” to read “Fire Code.”
- 1-327 **Sec. 1207.6.** In the first sentence, revise “(0.708 L/S/m²)” to read “(0.761 L/S/m²).”
- ## VOLUME 2
- 2-4 **Sec. 1611.7.** In the last sentence, revise the reference code section to read “Section 1613” instead of “Section 1615.”
- 2-4 **Sec. 1612.3.1.** Revise the last sentence to read as follows:

- “No increase in allowable stresses shall be used with these load combinations except as specifically permitted elsewhere in this code.”
- 2-5 **Sec. 1612.3.2.** In the first paragraph, second sentence, delete the comma following “combinations.”
- 2-12 **Sec. 1629.8.2.** In the third line, correct the spelling from “catetory” to “category.”
- 2-16 **Sec. 1630.8.2.2, Item 1.** Delete the words “or unreinforced masonry.”
- 2-16 **Sec. 1630.8.1.** Revise the last sentence to read as follows: “See Sections 1612 and 1629 for combining gravity and seismic forces.”
- 2-16 **Sec. 1630.9.1.** Revise the third sentence to read as follows: “Where Allowable Stress Design is used and where drift is being computed, the load combinations of Section 1612.2 shall be used.”
- 2-20 **Sec. 1633.2.5.** Revise the last sentence in the second paragraph to read as follows: “The force shall not be less than $0.3 C_a I$ times the dead plus live load.”
- 2-32 **Table 16-N, Footnote 6.** Revise to read: “Ordinary moment-resisting frames in Seismic Zone 1 meeting the requirements of Section 2214.4 may use an R value of 8.5.”
- 2-32 **Table 16-N.** Revise entry 3.4.b to reference “Footnote 8” instead of “Footnote 7.”
- 2-33 **Table 16-O, Footnote 4.** Change the reference from “Division VI” to “Division X.”
- 2-48 **Sec. 1809.5.1.** In the first sentence, revise the reference code section to read “Section 1605” instead of “Section 1603.”
- 2-49 **Table 18-1-A.** Revise the units in the third column title to read as follows: “LBS./SQ. FT./FT.”
- 2-101 **Sec. 1903.11.** In the first sentence, insert “P.C.I.” before “Manual 128.”
- 2-142 **Sec. 1915.2.2.** Revise the last sentence to read as follows: “External forces and moments are those resulting from the load combinations of Section 1612.3.”
- 2-156 **Sec. 1921.2.1.7(2).** Revise the second sentence under “connection design force” to read as follows: “ M is the moment developed at the connection when the frame is displaced by Δ_s assuming fixity at the connection and a beam flexural stiffness of no less than one-half of the gross section stiffness.”
- 2-159 **Sec. 1921.4.4.1, Item 1.** In the last sentence, revise the referenced formula from “Formula (10-5)” to “Formula (10-6).”
- 2-159 **Sec. 1921.4.4.1, Item 4.** In the last sentence, revise the referenced formula from “Formula (10-5)” to “Formula (10-6).”
- 2-160 **Sec. 1921.5.3.1.** In the last sentence, revise “confined is such” to “confined if such.”
- 2-161 **Sec. 1921.6.6.3.** In the last sentence, delete “Item 4.”
- 2-162 **Sec. 1921.6.6.5.** In the first paragraph, revise the reference code section to read “Section 1631.2” instead of “Section 1629.2.”
- 2-164 **Sec. 1921.8.6.1.** Revise the referenced formulas from “Formulas (9-2) and (9-3)” to “Formulas (12-5) and (12-6).”
- 2-221 **Sec. 2108.2.3.3, Item 2.** In the first sentence, revise “1.4E” to read “1.0E.”
- 2-221 **Sec. 2108.2.3.6.2, Item 3.** In the second sentence, revise “ R_w equal to 1.5” to “ R equal to 2.”
- 2-223 **Sec. 2108.2.5.6, Item 1.** In the second sentence, revise “ R_w equal to 1.5” to “ R equal to 1.1.”
- 2-224 **Sec. 2108.2.6.2.6(3).** In the first sentence, revise “ R_w equal to 1.5” to “ R equal to 1.0.”
- 2-256 **Sec. 2213.7.3.** In the second sentence, revise the reference code section to read “Section 2208 N7” instead of “Section 2251 N7.”
- 2-258 **Sec. 2213.9.1.** In the first sentence, revise the reference code section to read “Section 1627” instead of “Section 1625.”
- 2-258 **Sec. 2213.9.** Change “(SCFB)” after title to read “(SCBF).”
- 2-279 **Sec. 2315.2, Exception 2, Item 2.3.** Revise “0.005 times each story height” to read “0.0025 times each story height as defined in Section 1630.10.”
- 2-286 **Table 23-II-G, Footnote 3.** Revise to read as follows: “In Seismic Zone 4, the maximum ratio may be $3\frac{1}{2} : 1$ for walls not exceeding 10 feet (3048 mm) in height on each side of the door to a one-story Group U Occupancy.”
- 2-291 **Sec. 2316.2, Item 5.** Revise the first sentence to read as follows: “When using Section 1612.3.1 basic load combinations, the Load Duration Factor, C_D , noted in Table 2.3.2 shall be permitted to be used.”
- 2-300 **Sec. 2320.8.6.** In the first sentence, add “Section 4.4.1.2 of NDS-91” after “Part I.”
- 2-339 **Sec. 2321.2.** In the first sentence, revise the reference code section to read “Section 2303, Item 5” instead of “Section 2303.1, Item 5.”
- 2-385/6 **Sec. 3504, Part IV, Chapter 19.** Add the following recognized standard: “Recommended Practice for Glass Fiber Reinforced Concrete Panels, P.C.I. Manual 128-93 . . . 1903.11.”
- 2-402 **APPENDIX CHAPTER 16, DIVISION III.** Relocate Seismic Zone for Taiwan in Appendix to between Syria and Thailand.
- 2-408 **Sec. 1658.4.3, Item 1.** In the first paragraph, revise the reference from “Division III” to “Division IV.”
- 2-409 **Sec. 1659.2.** In the first paragraph, revise the reference code section to read “Section 1658.3.5” instead of “Section 1658.3.3.”
- 2-409 **Sec. 1659.2.** In the last paragraph, revise the referenced formula from “Formula (30-4)” to Formula (30-8).”
- 3-341 **Figure 21-1-1.** Revise the legend under “Weathering Regions” as follows: “Negligible Weathering” to “Severe Weathering” and “Severe Weathering” to “Negligible Weathering.”

VOLUME 3