

ICC CODE TECHNOLOGY COMMITTEE MEETING #17 April 9 – 10, 2009

DRAFT AGENDA

Doubletree Hotel – Birmingham 808 South 20th Street Birmingham, AL 35205 (205) 933 - 9000

Thursday, April 9: 8:00 am – 5:00 pm Friday, April 10: 8:00 am – 4:00 pm

- 1.0 Welcome and introductions Chair Heilstedt
 - 1.1 Call to order; introductions; welcoming remarks
- 2.0 Approve agenda
- 3.0 Approve minutes of CTC Meeting #16 November 12 13, 2008
- 4.0 Administration
 - 4.1 Welcome new CTC members
 - 4.2 Elect Chair/Vice chair
 - 4.3 New ICC Code Development Process
- 5.0 Climbable Guards
 - 5.1 Working meeting 2009/2010 cycle a. Follow up to E85 – 07/08 – seat board terminology
 - **5.2** Update Final Report May 2008 (5/21/08)
- 6.0 Child Window Safety
 - 6.1 Study group update /Working meeting 2009/2010 cycle a. Follow-up to RB 173 07/08
 - 1. Inconsistent IBC/IRC action
 - 2. Minimum sill height
 - 3. Update of ASTM F2090; inclusion in the code
 - 6.2 Develop Report
- 7.0 Care Facilities
 - 7.1 Study group update/Working meeting 2009/2010 cycle a. Comprehensive revision to care facilities
 - 7.2 Update Final Interim Report No. 1 dated 3/9/06
- 8.0 Review of NIST WTC Recommendations
 - **8.1** Working meeting 2009/2010 cycle
 - a. Follow-up to 07/08 cycle code changes:

S81: wind tunnel test standard S101: structural integrity FS 115: structural frame

G68/G69: density of sprayed fire resistive materials

E3/E4: evacuation plans

b. Ad Hoc Terrorism Resistant Buildings efforts on

CTC Meeting # 17 Draft Agenda Page 1 of 2 F 86: fire command center

G56: exit enclosure impact resistance

G58: stairway communication

G108: risk assessment

New: thermal expansion of floor systems

- 8.2 Update Final Interim Report No. 3 dated 3/15/07
- 9.0 Balanced Fire Protection (BFP)
 - 9.1 Vertical openings
 - a. Study group update/Working meeting 2009/2010 cycle
 - b. Develop Vertical Openings report
 - 9.2 Features
 - a. Study group report
 - **b.** Develop Features report
 - 9.3 Roof vents
 - a. Study group update/Working meeting 2009/2010 cycle
 - 1. Roof vents in unsprinklered buildings
 - 2. Code text vs NFPA 204
 - 3. Mechanical smoke exhaust
 - 4. Multiple vent operation
 - 5. Roof vents in high piled storage areas
 - 6. ESFR's and roof vents
 - b. Update Final Interim Report No. 1 dated 10/19/06
 - 9.4 Methodology
 - a. Determine future of effort
 - 9.5 BFP Overall
 - a. Working meeting Develop BFP progress report
- **10.0** Emergency Evacuation with Elevators
 - 10.1 a. Develop Report based on NIST WTC Recommendations area of study
- 11.0 Labeling of Fire Rated Glazing
 - 11.1 Study group update/Working meeting 2009/2010 cycle
 - 11.2 Develop Report
- 12.0 Unenclosed exit stairs
 - 12.1 Study group update/Working meeting 2009/2010 cycle
 - 12.2 Develop Report
- 13.0 New business
- 14.0 Old business
- **15.0** Future Meetings (tentative)
 - 15.1 Follow-up conference calls prior to code change deadline
 - **15.2** CTC Meeting # 18:
- 16.0 Adjourn

CTC website for posted materials: http://www.iccsafe.org/cs/cc/ctc/index.html