

2006 International Mechanical Code Study Companion
Errata to 1st, 2nd, 3rd and 4th printings

Study Session 5 Quiz, Question 20, Page 101

When serving a Type 1 Hood, a grease duct in a shaft enclosure that penetrates a ceiling shall have a minimum clearance of ____ inches from gypsum wallboard attached to noncombustible structures. (posted 11/1/2010)