

2006 IBC Handbook Fire- and Life-Safety Provisions

Errata to the First Printing

Section 414, page 72. Remove “Aerosols” from the list of Physical Hazards” (posted 11/1/07)

Section 1022.1, page 390. In Group I-3 occupancies where all exits may be satisfied through the use of horizontal exits, ~~Another difference is that~~ at least one of the exit paths from the area into which the horizontal exit leads must lead directly to the exterior or to an exit enclosure. ~~Therefore all egress from the refuge area cannot pass tough a corridor or intervening room prior to reaching an exit component.~~ Figure 1022-2 depicts possible arrangements for horizontal exits. (posted 1/18/08)