2009 International Building Code Errata

SECOND PRINTING (Updated March 22, 2010)

CHAPTER 14 EXTERIOR WALL

1405.6.1 Tolerances. Anchored masonry veneers in accordance with Chapter 14 are not required to meet the tolerances in Article 3.3 $\underline{\text{F1}}$ $\underline{\text{G4}}$ of TMS 602/ACI 530.1/ASCE 6.

1408.4.1 EIFS with drainage. EIFS with drainage shall have an average minimum drainage efficiency of 90 percent when tested in accordance the requirements of ASTM E 2273 and is required on framed walls of Type V construction, and Group R1, R2, R3 and R4 occupancies.