2009 International Mechanical Code Errata

1ST AND 2ND PRINTING (Updated September 21, 2010)

CHAPTER 15 REFERENCED STANDARDS

<u>-</u>			
UL1479-03	. Fire Tests of Through-penetration Firestops – with	Revisions the	nrough Apri
	2007	506.3.10.2,	506.3.10.3
UL2043-08	. Fire Test for Heat and Visible Smoke Release for I	Discrete Pro	ducts
	and their Accessories Installed in Air-handling Spa	aces	504 6 3

2009 International Mechanical Code Errata

1ST PRINTING (Updated September 21, 2010)

CHAPTER 15 REFERENCED STANDARDS

<u>UL2158A – 2006....... Outline of Investigation for Clothes Dryer Transition Duct........504.6.3</u>