


Significant Changes to the International Plumbing Code, International Mechanical Code, International Fuel Gas Code, 2009 Edition

Errata to the First Printing

Page 187 (404.4): Delete the illustration in its entirety, including the caption, and replace it with the following illustration. (Posted 8/4/09)



Underground penetrations prohibited

Page 189 (404.6): Delete the bottom illustration at the bottom of the page in its entirety, including the caption. (Posted 8/4/09)