

303.3

Errata 2024 ISPSC Chapter 3 General Compliance

Code: 2024 International Swimming Pool and Spa Code

Applies to following Printings: 1st and 2nd Printings

Section/Table/Figure Number: Section 303.3

Posted: March 2, 2026 updated April 10, 2026

Correction:

303.3 Residential pools and permanent residential spas. The energy consumption of *residential* swimming pools and permanent *residential* spas shall be controlled in accordance with the requirements of ~~APSP~~ [ANSI/PHTA/ICC-15](#).

Correlation Notes: None

305.4

Errata 2024 ISPSC Chapter 3 General Compliance

Code: 2024 International Swimming Pool and Spa Code

Applies to following Printings: 1st and 2nd Printings

Section/Table/Figure Number: Section 305.4

Posted: January 10, 2025

Correction:

305.4 Structure wall as a barrier. Where a wall of a dwelling or structure serves as part of the barrier and where doors, gates or windows provide direct access to the pool or spa through that wall, one of the following shall be required:

1. Operable windows having a sill height of less than 48 inches (1219 mm) above the indoor finished floor, doors and gates shall have an alarm that produces an audible warning when the window, door or their screens are opened. The alarm shall be *listed* and labeled as a water hazard entrance alarm in accordance with UL 2017.
2. ...
3. ...
4. ...
5. A *safety cover* that is *listed* and *labeled* in accordance with ASTM F1346 is installed for the pools and spas.
6. An *approved* means of protection, such as self-closing doors with self-latching devices, is provided. Such means of protection shall provide a degree of protection that is not less than the protection afforded by Item 1 or ~~2~~ 5.

Correlation Notes: None

306.6

Errata 2024 ISPSC Chapter 3

Code: International Swimming Pool and Spa Code

Applies to following Printings: 1st Printing

Section/Table/Figure Number: Section 306.6

Posted: June 7, 2024

Correction:

306.6 Gaps. Gaps not less than $\frac{1}{8}$ inch and not greater than $\frac{1}{2}$ inch shall be provided between wood deck boards for drainage. Gaps between manufactured deck boards shall be in accordance with the manufacturer's installation instructions.

Exception: Gaps are not required between wood deck boards installed on decks sloped in accordance with Section ~~R~~306.5

Correlation Note: None