U3 – UNDERGROUND TANK/PIPING TIGHTNESS TESTING JOB TASK ANALYSIS & EXAMINATION OUTLINE

	r, Closed Book Approximate % of 50 Qu ECORDS AND REPORTING REQUIREMENTS (Content Area)	estions 10%
0101	Line and Tank Tightness Test Records (Task) Review past tightness test records when available. Complete and submit tightness test resu current test to state UST agency on appropriate forms. Provide the tank owner/operator with v test results which indicate whether test is "passed" or "failed".	
0102	Reporting of Failed Results and Releases (Task) Notify the tank owner/operator that a "failed" test must be reported as a suspected release appropriate state agency within the appropriate time. Report system leaks as required.	4% to the
02 SI	TE PREPRATION AND LAYOUT (Content Area)	6%
0201	<u>UST System Layout</u> (Task) Determine site layout for tanks, piping, and equipment before beginning tests. Verify access to up test equipment.	6% o set
03 PL	LACEMENT OF EQUIPMENT (Content Area)	6%
0301	Tank Fill Lines, Devices, Connections, and Tank Caps (Task) Verify correct installation of tank fill lines, connectors and other devices. Verify elevation of pip Verify that fittings and joints are properly tightened. Verify correct identification and installation and monitoring well caps	
0302	Automatic Leak Detection Systems (Task) Verify compliance with regulations requiring installation and proper operation of line leak detection and automatic leak detection systems and devices for product piping and tanks.	4% ction
04 SE	ECONDARY CONTAINMENT (Content Area)	4%
0401	Tank and Overfill Protection (Task) Verify correct installation of tank overfill protection.	2%
0402	<u>Tank and Pipe Secondary Containment</u> (Task) Verify proper installation of tank and pipe secondary containment and release detection metho	2% ods.
05 V/	APOR RECOVERY SYSTEMS (Content Area)	4%
0501	Stage I and Stage II Vapor Recovery Systems (Task) Verify correct installation of Stage I and Stage II vapor recovery systems when required.	4%

	EST VARIABLES & LEAK DETECTION REQUIREMENTS (Content Area)	24%
0601	Release Detection Requirements (Task) Determine compliance with regulations requiring installation and proper operation of leak det	6% tection
	systems and devices for product piping and tanks.	
0602	<u>Test Methods</u> (Task)	4%
0603	Determine test methods to use to meet regulations. Periodic Tests at Required Intervals (Task)	4%
1003	Correctly inform tank owner/operator when a tightness test is required. Perform tightness test	
	required time intervals according to EPA regulations applicable to each situation.	
0604	Water Table (Task)	2%
	Determine the height of the water table and the groundwater elevation relative to the bottom	of the
0605	tank. Use methods to compensate for the effects of the water table on the tightness tests.	00/
	Interpretation of Test Results (Task) Determine whether or not the tightness test results are conclusive and whether additional test	8% sting is
	required to obtain valid results.	sung is
07 TA	ANK TIGHTNESS TESTING METHODS(Content Area)	14%
0701	<u>Tank Tightness Testing</u> (Task) Use various methods of tank tightness testing.	14%
08 HI	EALTH AND SAFETY FOR UST WORKERS (Content Area)	12%
	Control of Vapors and Sources of Ignition (Task)	
	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing,	
	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when	
08 HI 0801 0802	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing,	6%
0801	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect	6% 2%
0801 0802	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential.	6% 2% tricity or
0801	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task)	6% 2% tricity or 4%
0801 0802	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential.	6% 2% tricity or 4%
0801 0802 0803	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment.	4% lved in,
0801 0802 0803	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol	6% 2% tricity or 4%
0801 0802 0803 09 PI	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area)	6% 2% tricity or 4% lved in,
0801 0802 0803 09 PI	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install	6% 2% tricity or 4% lved in, 20% 4%
0801 0802 0803 09 PI 0901	<u>Control of Vapors and Sources of Ignition</u> (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install instrumentation equipment according to the test equipment manufacturer's instructions.	6% 2% tricity or 4% Ived in, 20% 4%
0801 0802 0803 09 PI 0901	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install instrumentation equipment according to the test equipment manufacturer's instructions. <u>Conduct Line Tightness Tests</u> (Task)	6% 2% tricity or 4% Ived in, 2 0% 1
0801 0802 0803 09 PI 0901	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install instrumentation equipment according to the test equipment manufacturer's instructions. <u>Conduct Line Tightness Tests</u> (Task) Identify and remove air and vapor pockets in the piping. Measure and record pressure ar	6% 2% tricity or 4% Ived in, 20% 1
0801 0802 0803 0901 0902	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install instrumentation equipment according to the test equipment manufacturer's instructions. <u>Conduct Line Tightness Tests</u> (Task) Identify and remove air and vapor pockets in the piping. Measure and record pressure ar volume loss or gain during tightness testing. <u>Compare Data to Threshold Values</u> (Task)	6% 2% tricity or 4% lved in, 2 0% 1 10% nd
0801 0802 0803	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol- including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install instrumentation equipment according to the test equipment manufacturer's instructions. <u>Conduct Line Tightness Tests</u> (Task) Identify and remove air and vapor pockets in the piping. Measure and record pressure ar volume loss or gain during tightness testing. <u>Compare Data to Threshold Values</u> (Task) Compare measured leak rate to the acceptable threshold values to determine if there are	6% 2% tricity or 4% lved in, 2 0% 1 10% nd
0801 0802 0803 0909 0901 0902	Control of Vapors and Sources of Ignition (Task) Identify and control concentrations of flammable or combustible vapors before repairing, decommissioning or tank and pipe tightness testing. Use breathing support devices when necessary. Remove sources of ignition within distances required. <u>Grounding and Bonding of Equipment</u> (Task) Verify grounding of electrical equipment to minimize the possibility of sparks from static elect other differences in electrical potential. <u>Personal Safety Equipment</u> (Task) Observe safety precautions and use personal safety equipment necessary for the work invol including the use of protective clothing, safety line and other recommended equipment. PE TIGHTNESS TESTING METHODS (Content Area) <u>Preparation for Pipe Tightness Testing</u> (Task) Identify components and system type and prepare piping for testing. Calibrate and install instrumentation equipment according to the test equipment manufacturer's instructions. <u>Conduct Line Tightness Tests</u> (Task) Identify and remove air and vapor pockets in the piping. Measure and record pressure ar volume loss or gain during tightness testing. <u>Compare Data to Threshold Values</u> (Task)	6% 2% tricity or 4% lved in, 2 0% 1 10% nd